

BS2P40 to UART connections

Pin #	Name	Connection	Pin #	Name	Connection
1	R2IN	DB9 (RX)	15	DIN	Stamp P7
2	R2OUT	Pin 11	16	DOUT	Stamp P6
3	T2IN	Pin 12	17	SCLK	Stamp P5
4	T1IN	Pin 14	18	CS	Stamp P4
5	R1OUT	Pin 13	19	IRQ	Stamp P3
6	R1IN	DB9(RTS)	20	SHDN	+5V
7	T1OUT	DB9 (CTS)	21	V+	N/C
8	Vcc	+5V	22	C1+	N/C
9	X2	Crystal	23	C1-	N/C
10	X1	Crystal	24	C2+	N/C
11	CTS	Pin 2	25	C2-	N/C
12	RTS	Pin 3	26	V-	N/C
13	RX	Pin 5	27	GND	Ground
14	TX	Pin 4	28	T2OUT	DB9 (RX)

